D C I Digital Cinema Initiatives, LLC

ERRATA TO DCI DIGITAL CINEMA SYSTEM SPECIFICATION, VERSION 1.4

Errata items continue to be evaluated and will be posted after agreement by the DCI membership that the specific erratum needs to modify the DCI *Digital Cinema System Specification, Version 1.4, dated 20 July 2020.* Suggested Erratum issues may be emailed to dci.info@dcimovies.com. Please include "Errata" in the subject line.

DCI SPECIFICATION ERRATA LISTING

6 JANUARY 2021

Erratum Number	Spec. 1.4 Page No.	Section(s) Affected	Description
16	106	9.4.3.5	The final sentence of item #5 is replaced and clarified with:
			The SM shall disallow or terminate playout of encrypted content when any of the image and sound integrity pack metadata is not present per the requirements of Section 5.3.2.1 MXF Track file Encryption – Introduction.
			For purposes of clarity, while detected deviations in integrity pack metadata does not impact playout, the SM shall disallow or terminate playout should it detect any missing integrity pack metadata for the encrypted frame currently being processed. The SMS may direct the SM to resume playout from a subsequent track file frame location. However, playout shall be subject to the same requirement.
17	134	9.4.6.3.8	The heading "IMB" of Table 19 is replaced with "IMB or IMBO"